

# Diagnosis

## Bilateral HTO

Left

HKA : 182°

Correction : 6°

Tibial Slope : 5°

Correction : 4°

Right

HKA : 182°

Correction : 6°

Tibial Slope : 5°

Correction : 4°

# Solution

## HTO with PSI

High Tibial Osteotomies  
combined with patient specific guide



Left



Right

FIND OUT MORE WITH

NEWCLIP-TECHNICS



Newclip Technics  
PA de la Lande Saint Martin  
45 rue des Garottières  
44115 Haute - Goulaine  
**+33 (0)228213712**  
[www.newcliptechnics.com](http://www.newcliptechnics.com)